

without special condition

18213

61581 Lora

yard repaired with doubling plate. Fore top repaired
Cap shroud & upper topsail renewed, and a number
of minor repairs to mast gear & rigging

Wear & tear The wood, fore topmast has been re-
newed. Both arms of fore lower
yard & star^d gun of lower topsail repaired with
doubling plates where thin.

See Orinadin report No 257

All damage has now been made good as follows;
Leak wood rail around poop. steering gear cover,
companion doors, top & ends, renewed. Port main brace
lumpkin & three wash parts repaired & some other
minor repairs made.

ACT

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation