

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 14th Dec 99 When handed in at Local Office 15 is Port of London
 No. in Reg. Book 515 Survey held at London Date, First Survey 27th Nov 9 Last Survey 9th Dec 1899
 on the Wood, Iron or Steel S.S. "Hirondelle" Master C. Jostling
 TONNAGE:— Built at Dunee By whom Gourley Bros When 1890 - 6
 GROSS 1607 Owners General Sim. Nav. Co. Port belonging to London
 UNDER DECK 1198 Owners' Address
 NET 817 (if not already recorded in Appendix to Register Book.)
 Surveyed Afloat or in Dry Dock? Name of Dock Deptford Green Destined Voyage Bordeaux

WB=Cell DBor DBa 220 feet; uE&B 220 feet; f 220 feet; }
 total capacity 310 tons. FPT 220 tons; APT 220 tons; MT 220 tons. }

N.B.—All alterations in the existing records should be underlined.
 If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 61036 Port Lon

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR advancement of S.S. No. 2.

Vessel placed in Dry Dock — the bottom found in good condition, recreated.
 The S.S. No. 2 due 6.98 partly held last April by examination of bottom in Dry Dock, has now been advanced as follows: — Holds, peaks, cross side bunkers cleared, ceiling lifted as required (with exception of upper bunker between main bridge decks) and with the CB space sealed & recreated as necessary; ceiling lifted and all double bottom tanks examined internally & tested; masts, rigging & pumps, sluice valves, RT doors, equipment and decks (except main deck in way of upper bunkers) examined.

Repairs due to wear & tear: Some close ceiling renewed; bunker bulkheads repaired, 1 chain plate renewed & minor repairs.

To complete Survey: Bunker space between main bridge decks to be cleared & examd. It is stated this will be done on vessel's return about middle of next week.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items.
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								
PRESENT CONDITION OF THE								
Decks	Good	Stringers	Good	Engine Room Skylights	Good	Boats	Good	
Caulking of Decks	—	Inner Bottom Plating	—	Coal Bunkers, Open'gs, Lids, &c.	—	Masts, Yards, &c.	—	
Waterways	—	State if Tanks now tested	Yes	Scuppers	—	Condition, how ascertained	By ramming	
Coamings	—	Bulkheads	Good	Cargo Hatchways	—	(State if wedges removed)	no	
Beams & Fastenings	—	Ceiling	—	Hatches	—	Sails	—	
Outside Plating	—	Cement or Asphalt (State which.)	—	Planking of Wood Vessels	—	Equipment letter	"H"	
Caulking of ditto	—	Rudder	—	Tree-trunks ditto	—	Anchors, No. of	3 B. 15. 1 K	
Rivets	—	Windlass	—	Breasthooks & Stems ditto	—	Cables (State if now ranged)	no	
Breasthooks & Crutches	—	Have Pumps now been examined and found efficient?	Yes	Transoms, Pointers, & Crutches ditto	—	" length (on board)	—	
Transoms	—	Have Sluice Valves now been examined and found efficient?	Yes	Timbers of Frame at openings ditto	—	" Rule length (per Table 22)	—	
Frames	—	Have Watertight Doors now been examined and found efficient?	Yes	Ditto ditto at other places ditto	—	Hawsers & Warps	Good	
Reverse Frames	—	Dblg. Plates under Sounding Pipes	Yes	Salting (State if examined.)	—	Standing & Running Rigging	—	
Floors	—			Copper, or Y.M. (State if on felt.)	—			
Keelsons	—			When put on, Month	Year			

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel appears to be in a good efficient condition eligible in my opinion to remain as classed and to have record of survey 12.99 on notation of S.S. No. 2-99 when the Survey has been completed by examination of bunkers between main bridge decks.

Office Fee (if chargeable) per Scale II., Sec. 27	£	5	10
Survey Fee (per Section 28)	£	10	11
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	4	19
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Fees applied for,

16 Dec 1899

Received by me,

571 18.00

JAN

11

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

TUES. 19 DEC 1899

Deferred for

comp. of N.2

+ LMB. 12.99

WED. 27 DEC 1899

FRI. 26 JAN 1900

TUES. 9 JAN 1900

FRI. 12 JAN 1900

Lloyd's Register Foundation

LON 720-0206