





on acc. of damage by collision:-  
Center shaft, found fractured at fore end  
of after liner, now renewed, and smaller  
repairs effected.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Bd. Bolers examd and valves adjusted.

It is submitted that  
this vessel is eligible for  
THE RECORD. B.S. 12.99.

C.M.  
28.12.99

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation