

2nd Number

45512

Managers

(Where necessary to be entered)

F.E.

Inspected by Chief Surveyor 25.8.98

Received from Chief Surveyor

L'S NAME *St. S. Tuscarora*Report *Std* No. 19342

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>3/20"</i>	<i>Proportion</i>
Spar Sheerstrake . .		
Description of Framing:— <i>Ordinary</i> , (viz., ordinary, deep, zed, channel or bulb-angle).		

On this vessel being placed in dry dock at Wallasey for cleaning & painting some damage was found to have been sustained to the bottom, and the following repairs have been done per Newcastle report 37088 attached:— 1 plate removed, faired and replaced, 1 plate faired in place, 1 frame repaired and minor repairs.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\pm$  100 A1 ("Steel") "Carrying Petroleum in bulk" as recommended.

$\pm$  100 A1 ("Steel") "Carrying Petroleum in bulk":

2 DRs (Stl) & web frames & shelter dk (Stl-pt ws)

N.B = Cell DB & E 44' 2276 FPT 2866 APT 966

FK. 18BH. Ccm. LA & CP.

*C. H. J.*

25/8/98



© 2021

Lloyd's Register Foundation

SLD1012-0151

dth &amp; thickness

" Hold

Quarter 'tween Dks.,

" in Hold

B-FRAMES, In Fore Body. No. and spacing

" \*Deck, Material and thickness

Forecastle Deck Stringer Plate, 1111 &amp; 1112