

"Leechmere"

746

They found several defective rivets in shell  
rudder. It was also recommended that  
rudder should be lifted + rebushed.

29:4:89

SLD 63-0196