


No. 3940.

(Received in London Office,



TESTS OF BOILER STEEL.

Tests of 4 Steel M. manufactured by The Steel Co. Scotland of Blackburn
 for Boiler No. 940 to be constructed by Blair Ho Lun of Stockton
 for Messrs Withy & Co's No 142.

Date first visit _____ last visit _____ No. of visits _____

The _____ specified in the accompanying copy of Advice Notes were rolled from
 _____ charges. The tensile test has been applied to 2 samples as set forth below,
 and the temper and bending tests satisfactory


When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
	<u>Turnace Crown</u>	<u>F 910</u>	<u>8634</u>	<u>59</u>	<u>1.13</u>	<u>667</u>	<u>18.9</u>	<u>28.3</u>	<u>27.</u>		
	<u>do.</u>	<u>0207</u>	<u>8649</u>	<u>56</u>	<u>1.13</u>	<u>633</u>	<u>18.12</u>	<u>28.6</u>	<u>21.</u>		

D.P.
18/10/86

Fee £ : :
 Expenses £ : :
 £ : : _____

To be paid by _____


 Surveyor, Lloyd's Register,
Glasgow.
 Foundation
16/10/86