

Pt. Twin Pt. m/v ELKHOUND


Br Rpt RP/2282

It is concluded the inner ^{top surface} surface of the bottom plating
clear of the oil tanks is covered with cement, and that
the stream wire or chain has been supplied as required,
but the Surveyor should be requested to state if this is
so + forward particulars of same.

For Br 11/129

W.H.

21.10.29.



© 2020

Lloyd's Register
Foundation

W100-0036