

UNDER DK. 8338
NET 5792

Managers -

(if not already recorded in Appendix to Register Book)
Port belonging to London

Surveyed Afloat or in Dry Dock? Afloat Name of Dock At Saint John, N.B. Destined Voyage

TERMS ARE CONTINGENT UPON SATISFACTORY CONTRACT. ALL CONTRACTS AND AGREEMENTS CONTINGENT UPON STRIKES, ACCIDENTS AND OTHER CAUSES BEYOND OUR CONTROL. ALL QUOTATIONS ARE SUBJECT TO CHANGE WITHOUT NOTICE.

3 - FEB 1948

Saint John Dry Dock Co. Ltd.
Shipbuilding and Repairing
Structural Steel Work, Dredging and General Engineering

PLEASE ADDRESS ALL COMMUNICATIONS TO THE COMPANY

CABLES:
"DRYDOCK", SAINT JOHN

East Saint John, N.B.
January 12, 1948.

Master & Owners,
S/S "PORT MELBOURNE"

Dear Sirs:

This is to certify that on Friday, the 9th instant, I made an underwater examination of the port and starboard propellers and the rudder on the above vessel at Berth No. 9, West Saint John.


One blade on the starboard propeller was found to be damaged and broken at the tip, approximately 8" wide x 1" deep.

No damage could be seen on the port propeller or the rudder and they appear to be in order.

Yours truly,

George Cossaboom
Geo. Cossaboom
Diver

LM



© 2019

Lloyd's Register
Foundation

THIS VESSEL AS NOW SEEN IS IN EFFICIENT CONDITION AND ELIGIBLE IN MY OPINION TO REMAIN AS CLASSED WITH

record of survey, subject to rudder etc. being specially examined at next drydocking (collision); also

may have been previously recommended.