

Received from Chief Ship Surveyor
S NAME At 1/5/5 "Star of Victoria" Rpt. Del No. 7930
Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Board
76359

of "Star of Victoria" pt Entry

Owing to pressing need of vessel
to secure cargo the Survey could not
be completed.

The ash chocks could not
be tested and the w.d doors on Bunker
bulkhead tried, owing to coal in bunkers.

The slight leaks observed
under the shelter deck have been touched
up, but a thorough test could not be
obtained as the cargo loading was
proceeding, and a proper water test would
probably have caused damage to tugs
lying in barge round the vessel.

The owners are aware of
these circumstances, and will comply
fully with these small matters im-
mediately on vessel return

GHR
5/2/19



Lloyd's Register
Foundation

22
Poop Deck, Angle, Bulk Angle, Plate,
Tee Bulk on Channel
Angles on upper edge

28

Angles on deck
Tie Plates
Deck. Material and thickness
Bridge Deck Stringer Plate

OBJECTIVE