

CLAN FARQUHAR

F.E.

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME: *Sheels War Scarus*

Rpt. *Bel*

No. *8030*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *90.*

Depth "d" *19.42*

Table No. *3. page 16*

Description *Bulk Angle as approved*

Longitudinal No. *40500.*

Proportions Length = *11.25*
Depth =

Sheerstrake *as approved.*

Downton pump & keel Anchor disposed with as approved in Standard Vessels.


This vessel appears to have been built in accordance with the plans and the approved plans, and it is submitted she is eligible to be classed *100 A1 (Steel) Shelter Deck* with freeboard," as recommended. The Summer freeboard of *11.1 1/2* from centre of disc to top of statutory deck line at *Shelter* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and entered in the Register Book, and further, the remaining freeboards, shown on the accompanying verification form to be inserted in the certificate of classification.

2 Ds (Steel) + Shelter Ds (Steel)

Cell No 392 14616 D.T. 39 11165 F.P.T. 1196 A.R.T. 766

F.K. 8 BH 6 Shelter Ds. pl. Cam. Repaired. P. 31 F. 43 Shelter Ds.

Carrying at full F.P. above 150°F in D.B. & D.T.
Certificate of Classification, to be endorsed *in bulk Ds. & Shelter Ds.*
battens not fitted," and the same
to be printed in the Register Book.



© 2020

Lloyd's Register Foundation

It should be pointed out to the Surveyors that the
number of shakes of shell plate ^{is} given in the report do
not agree with the appended sketch of missing section
& they should be requested to state which is correct.
The sketch of missing section should be
returned for their information & guidance.

M



© 2020

Lloyd's Register
Foundation

11007-0035-2/2