

"MATRONA"

Liv. 126758

(ex "Aba")

Notation of "Examined 4.46" is assigned.

The class is subject to buckled main deck stringer and adjacent plates (p.s.amids.) and stem and stem plating being repaired, bottom and floors in No.5 D.B. tank (p.s) being dealt with and indented shell plates C.10, D.9, H.7, 11 & 15 and J.15 (s.s), No.3 in 2nd and No.2 in 3rd strakes below sheer etc. (p.s) and shell plating in 2nd and 3rd strakes below sheer etc. (s.s. amids.) being permanently repaired at the first convenient opportunity.

The LIVERPOOL Surveyors report PERIODICAL SPECIAL SURVEY (D) due 11.42 commenced by the examination of decks, 'tween decks, Nos. 1 & 5 lower holds No.1 D.B. tank, after peak tank, after peak spaces, and recommend repairs to deck plating in way of refrig. spaces, and connections of frame (in No.1 lower hold to tank top).

During the period the vessel was under-going Survey, she overturned and subsequently sank. Salvage operations are now proceeding, but no information is available as to her future position.

The LIVERPOOL Committee have forwarded the above for the information of the COMMITTEE.

The case is SUBMITTED for the consideration of the COMMITTEE.

BM.

16-4-48.

BM

? Copy of finding survey.



© 2020

Lloyd's Register
Foundation

L11012-0201

Record ~~FRI.~~ 23 APRIL 1948.

'Unrepaired
casualty'

Copy
for reprint

L. Lloyd's 24/4.

ML
pic

WRR



© 2020

Lloyd's Register
Foundation

MADE AND PRINTED IN ENGLAND.
(As on or below the space for Committee's Minutes.)

If so, is the Report sent now, or when will it be sent?

REPAIRS, NOW

NOTE: *and*

SUMMARY

Rent

Renn

PRESENT

Decks

Caulking o

Coainings

Beams & h

Outside Pie

"

Frames

Reverse F

Longitudin

Transvers

Floors

Keelsons

Stringers

Inner Bo

Have the

Have the

Gen

at

Survey

Last K

N.B.

On