

16 AUG 1946

Rpt. 8.

(Received at London Office.....)

No. 8351

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 22nd July 1946 When handed in at Local Office 22nd July 1946 Port of Baltimore, Md.
No. in Reg. Book 24019 Survey held at Baltimore, Md. Date, First Survey 1st July Last Survey 6th July, 1946
(No. of Visits 3)

on the Wallsend Steel S.S. "HOPESTAR"
TONNAGE:— Gross 5267 Built at Newcastle By whom Swan, Hunter & Wigham Richardson When 1936 MONTH 2
ROSS 5267 Owners Wallsend Shipping Co. Ltd. Owners' Address -
NDER DK 4385 Managers Stott, Mann & Fleming, Ltd. (if not already recorded in Appendix to Register Book).
ET 31.92 Port belonging to Newcastle
urveyed Afloat or in Dry Dock? afloat Name of Dock Locust Point Port Covington Destined Voyage -

llDBorDBa - feet; uE&B - feet; f - feet
al capacity - tons. FPT - tons; APT - tons; MT - feet - tons.

Only alterations in the existing records of tanks should be inserted.
N.B.—All alterations in the existing records should be underlined.

ast Report, No. 113919 Port Lon

iodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined -

Not required

Was a damage report made by anyone else? if so, by whom? -

PAIRS, OR EXAMINATION AS PER RULE, FOR Repairs.

Requested by Master to attend and witness testing of No. 4 (p) double bottom tank in way of the deep tank ter repairs effected to tank top and margin plate in London. Testing satisfactory at this location but tank top at p of bracket of forward bulkhead web leaking - now welded and reinforcing welded doubler fitted and tank retested.

Master states vessel recently completed special survey at Newcastle, April 1946

Fair water plates at upper part of rudder stock renewed and resecured.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

ks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
lking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month
nings	Cement or Asphalt	Oil Bunkers	Boats
ms & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
side Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
nes	Have pumps been examined and found efficient?	Planking	Anchors, No. of
erse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
itudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr. (on board)
nsverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
rs	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
lsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
ngers		" " at other places	Standing and Running Rigging
er Bottom Plating		Stringers, Clamps & Shelves	Sails
the Tanks been examined internally?		Salting (State if examined.)	
the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel, being now so far as seen, in good condition appears worthy to remain as classed without fresh record of survey, subject to indented plating etc. (p.s.) in way of Nos. 1 & 2 holds and bottom plating etc. (p. & s.f.) and bulkhead (p.s.) aft end No. 1 hold being permanently repaired at first convenient opportunity.

ey Fee (per Section 29)	£	:	:	Fees applied for, July 23 1946
Special Damage Repair Fee (if any) (per Sec. 29)	£	:	70.00	Received by me, 19
Late Fee	£	:	10.00	
Travelling Expenses (if chargeable)	£	:	5.50	
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute

NEW YORK JUL 31 1946

Character Assigned

As now subject.

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

W1013-0047