



December 4, 1944

(W.F.)

RECEIVED:

REGISTRATION DR No. 816

assigned) as }
now verified }-----f

cent to
e vessel

(p.&s.f.

to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "HOPESTAR"..... REPORT..... Bos. No. 3950.....

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

(1st No. 2 SURVEY ^{COMMENCED} ~~PARTLY HELD.~~) Condition.

due 2.11. When proposed to be completed.....

on of Survey held, &c. Examination of shelter tween deck and starboard pocket bunkers

Subject to permanent repairs to indented shell plating in way of Nos.1 & 2 holds (p.s), ~~to~~ to indented bottom plating at the first convenient opportunity, and to starboard deep tank after bulkhead on return to the U.K.

S.S. PART HELD.

8.1.45

© 2020



W1013-0097

Lloyd's Register Foundation

Several tubes, staybolts, seams and rivets in three

combustion chambers leaking. have been carried out and

A number of tubes in inboard furnace leaking at the

(elt.)
th

scertained
(es removed.)
at

now ranged).....
mean di
d)
h

ng and Running Rigging

Register Book consequent up
as classed and to have recor