

total capacity tons. FPT tons; APT tons; MT feet tons.

N.B. - All alterations in the existing records should be underlined.

precisely as in Register Book

Report No. 9296 Port L.A.

# 100 A1

WORKS:  
TRAFFORD PARK, MANCHESTER.

LONDON OFFICE:  
BUSH HOUSE, ALDWYCH.

# THE SUPERHEATER COMPANY LTD

ST. MARGARET'S ROAD,  
BOWDON,  
ALTRINCHAM, CHESHIRE.

TELEPHONE:  
ALTRINCHAM 3381 (2 LINES)

YOUR REF. ....

OUR REF. WAJ/RH. 1494OM.

Lloyds Register of Shipping,  
71 Fenchurch Street,  
LONDON, E.C.3.

15th May, 1941.

Dear Sirs,

s.s. "HOPESTAR".  
Desuperheaters.

We have received an order from the Wallsend Slipway and Engineering Co. Ltd., for desuperheater coils for fitting inside the two main boilers of the above Vessel.

These coils are similar to those we originally supplied when the Vessel was built in 1935, and will be made as shown on the following prints now enclosed in triplicate :-

- MN.12950 - Arrangement of Coils fitted in the Boiler.
- MB.14290 - Details of Coils.

The tubing for this order will be taken from our stock being made from solid hot drawn mild steel 1.3/4" o.d. x 8 w.g. and 2.1/4" o.d. x 0 w.g., having been made by one of our usual suppliers to our Specification X41, mechanical test and chemical analysis certificates being available at our Works.

We have also been instructed to supply replace combustion chamber superheater elements for this Vessel and hope to send you shortly drawings regarding same for your approval.

In the meantime, we should be obliged to have one of each of the enclosed prints stamped as approved and returned to us in due course.

Yours faithfully,  
FOR THE SUPERHEATER COMPANY, LIMITED.

ENCL.



© 2020

W1013-0138

Lloyd's Register Foundation

between Nos 1 and 2 holds being dealt with at Owner's convenience, and indented shell plating and to repair permanently first convenient opportunity as previously recommended also to scupper pipe & ...

RD  
41  
NS NOT  
EX OF REPORT  
Closed 'A'  
f assigned) as  
now verified  
KHEADS  
ed record  
ventilate  
equipment  
Report  
per, or Y.M. of W  
(State if on Feb  
When put on, Mo  
its  
sts, Yards, &c.  
dition, how ascert  
(State if wedge  
ils  
quipment letter  
chors, No. of  
ain Locker  
bles (State if no  
length Sta  
(on board  
Rule length  
awser & Warps  
anding and Runni  
n the Register  
aim as classed  
as now c  
ted plating

Referred to the Chief Engineer Surveyor,

*[Handwritten signature]*

116 MAY 1941



© 2020

Lloyd's Register

Report,

W.B = Cell D Bor'D B  
total capacity  
X.R. - All alterations &

ter Ink. (MAD)  
low the space for

*between Nos 1 and 2*

Observations  
State clearly when  
survey, thus, for  
1, 2, 3, or "to refer  
well as they

Plating

at damaged

es

in way of sidelights.

ings Part B

NDITION OF THE

id and Paired or Rep

DAMAGE REPA

clearing of

ill found

is good,

OR EXAMIN

TWEEN

cases where t

his services for

urveys, when h

he Surveys sho

examinations a

separated from

ed in the form

clearly stated t

this case, .....