

-4 APR 1939 1

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "Hopestar"

Rpt. No. 97290

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.

Damage through heavy weather.

now repaired as follows:-

	Shell Plates	Main Frames	R Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck plates	Beams
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:-

Vessel examined in dry-dock, the bottom cleaned & coated & repairs effected to the fore peak bulkhead.

On account of wear & tear some hatch covers have been renewed & minor repairs effected.

The Owners Superintendent states it has been decided not to refit the cargo battens meantime.

It is submitted the vessel is worthy to remain as classed with record of Survey 3.39

100A1.
With freebd.
3.39 of we.

Handwritten signatures and date 30 3.39.

delete from S.R.L.

X The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book X



© 2020

Lloyd's Register Foundation

W1013-0297

Special Traveller Second