

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" Donkey " " "

as not done state for what reasons?

4 E

Chief Engineer Surveyor _____ Received from Chief Engineer Surveyor _____

NAME "HOPESTAR" Rpt. Nwc. No. 97290 Rpt 9

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Survey REPAIRS TO ENGINES AND BOILERS DUE TO ~~DAMAGE THROUGH~~ WEAR AND TEAR.

Intermediate shaft bearings removed and replaced by water-cooled bearings.

Safety valves renewed.

It is submitted the vessel is eligible to remain as classed without fresh record.



W1013-0299

3.4.39.

the aftermost ped. brg (on TS.) has been fitted with water cooling. New Safety Valves complete have now been fitted to the two Ma and the valves were afterwards adjusted under steam as stated

good steam? 28 team? ✓ the after end o ntly lubricated end of } ricated? } of screw shaft ed? Yes