

4m,9,35.

11 DEC 1936

1

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

M/S HOPESTAR

Rpt.

NWC

No.

94435

Apr 8

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Nature of Survey

Damage through

grounding (see Bdx Rpt 4819)

now repaired as follows:-

| | Shell Plates | Main Frames | R Frames | Floors & Bracket Floors | Inner Bottom Plates | Deck Plates | Beams |
|-------------------------------------|--------------|-------------|----------|-------------------------|---------------------|-------------|-------|
| Renewed | | | | | | | |
| Removed and faired or repaired..... | | | | | | | |
| Faired or repaired in place..... | | | | | | | |

Other items:-

Vessel placed in dry dock, no damage found.

Minor alterations carried out

Bottom cleaned specially in way of slight signs of pitting & specially coated.

It is submitted the vessel is worthy to remain as classed with record of Survey 11.36

100A1 with freeboard 11.36 NWC

NWC
[Signature]
4.12.36

S.R.f. - delete "drydocking (grounding)"



© 2020

Lloyd's Register Foundation

W1013-0319