

Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?
Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

4 E

of Engineer Surveyor

Received from Chief Engineer Surveyor

AME "HOPESTAR"

Rpt. Nwc

No. 94435

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

he endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH GROUNDING.

The class is subject to the machinery being examined on account of grounding.

Superheater tubes now renewed and minor repairs effected.

Additional lubricating oil and sanitary pumps fitted.

It is submitted the vessel is eligible to remain as classed without fresh record of survey and without special condition.



© 2020

Lloyd's Register Foundation
10.12.36.

W1013-0322

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent on any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, &c.)

140 lb., F.D., &c.)

ey Boilers?
key Boiler?
key Boiler?
e fitted at the a
being efficiently
t the after end
efficiently lubricat
ter bearing of so
power fitted?
d and
section w
ary mo
ry Pump
nd Fri
mpo h
mpo fit
te two
Comb.
mb. ch
Main