

2m,11,35.

5 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

20 MAY 1936

VESSEL'S NAME

Hopestar

Rpt. P. H.

No. 2564.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey

~~DAMAGE &~~ WEAR AND TEAR.

A number of superheater elements found to have swelled & cracked at the welded joints.

All superheater elements removed from boilers.

A number of leaking screwed flanges dealt with.

It is submitted the vessel is eligible to remain as classed with an ~~am~~-fresh record of Survey as recommended.

Elements swelled to  $1\frac{15}{16}$ ".

Elements swelled to a max. of  $1\frac{15}{16}$ ".



20/5/36.

Lloyd's Register  
Foundation