

Also, what special means, in the opinion of the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?
State latest date of internal examination of each boiler. **Both. 8-10-48.**

Present condition of funnel(s). **Efficient**

2 E

22 NOV 1948

Inspected by Chief Engineer Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME "COLWITH FORCE".

REPORT Sws.

No. 24209.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.


(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/92.)

of Survey ~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 24209~~

This Survey, due 6.48 ^{now} ~~partly~~ held ^{new}

completed, and the following repairs carried out (due to wear & tear):-
minor

It is submitted the vessel is eligible to remain as classed, with notation of B.S. 10.48 as recommended.



© 2020

Lloyd's Register
Foundation

W1015-0162

2.11.48

er steam? 180
steam? -
?
?
?
the after end
lently lubricat
er end of {
bricated? }
g of screw sha
tted
neir pri
newed.
efitted.