

COPY

SUVA,

26th August, 1931.

At the request of the Master of the Auxiliary Schooner "JOHN WILLIAMS V", WE instructed Captain E.W.G. Twentyman, Marine Surveyor to Lloyd's Agents in Fiji, to survey the four lengths of cable chain which had been imported for the use of this vessel.

Captain Twentyman's report is attached hereto, and we feel that full dependence and reliance can be placed therein.

MORRIS, HEDSTROM, LIMITED

PER: (Signed) (illegible)

LLOYDS AGENTS FOR FIJI.

Our Fee for Certificate and Report in

duplicate 10/6.

Encl:



© 2019

Lloyd's Register Foundation
w/1017-0045

| | | | | | | |
|-----------------------------|---|---|-----|--------------|-----|--------------------------|
| Side Stringer, Angles..... | 4 | 3 | .30 | 3/2 x 3 x 30 | | |
| " " Intercostal Plate | | ✓ | | | " " | Stiffeners, Spacing..... |