



Three Masted Schooner "JOHN WILLIAMS V".

It is submitted the Glasgow Surveyors might inform the Builders that this vessel already has the Figure "I" for equipment in her classification in the Society's Yacht Register, and while it is noted that at the Owners' request it is now proposed to supply two additional 30 fathom lengths of chain cable, (it is not the practice of the Committee to make any alteration to the record in the Book.)

Note will be made of this addition to the chain cable, although at the same time it may be observed that the Society has no Surveyor stationed at Suva, and no indication is given as to when it will be possible for one of the Society's Surveyors to verify the fact that the additional chain has actually been placed on board.

 27.5.31.



© 2019

Lloyd's Register  
Foundation

W6017-0058