

and subsequent repairs. Repairs on account of the body of the report, should be summarised in the form shown below. Whenever the other causes; and besides being detailed in the body of the report, should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Examined 8.15.
Fitted for oil fuel

PACIFIC STEAM NAVIGATION COMPANY

(INCORPORATED BY ROYAL CHARTER 1890)

PACIFIC BUILDINGS "H" Dept.

25th October,

50

CAS.63/50.

CARDIFF.


71418

S.S. "ORBITA"

Ship arrived at Cashmore's Yard, Newport, 12th October, 1950.

WKR

THE PACIFIC STEAM NAVIGATION COMPANY



© 2020

Lloyd's Register
Foundation

SECRETARY TO THE
LIVERPOOL COMMITTEE

W1025-0185

W1025-0184

main
mined
after
cking.
P.P.

It would appear
the vessel is
eligible to have

the impressions no longer removed from hatchways