


Nam Bukal

Please attach the shafting plans
referred to in the report.

Send Repairs Plans
to Mr. Heen.



© 2019

28/4/44
Lloyd's Register
Foundation

W103-0005

liary compressors.

2 *Steam*

ting air receivers.

3 *Main*, 3 *Aux.*

ction air receivers, Main Engines.

None

connections. 4.35 8.37

s. 2 *Circ.* 1 *High*, 1 *Ball*, 1 *Swivel*, 1 *Saw* 9.37
for *Serv.* 12.36

fuel storage tanks.

eller and outside fastenings.

Lon. 3.35 Mel 11.35 Lon. 12.37
Huc 4.35 Lon 2.36 Mel. 9.36 8.138
dir 9.37 C. 3.36 Lon. 3.37
Mel. 4.36 Mel. 5.37
2. 12.36

submersible
No. 1 (outboard) 12.36

Gen. (in) 8.37

P.S. 12.37

Clay. Port 5.37

Aux. Engines.

3

Pumping arrangements.

P. alt 11.35
P. 7.37
Start. 5.36

9.36. No 1 *ford* *Donkey* *feed* 8.37

Daily Service tanks.

3.37, 5.37
5.33

Elec. Fittings

Light *8.37*
7.37 *Whight* *1.37*

Foundation