

Rpt. 8.

WRECK SECTION

No. 575 (Received at London Office)

No. LA. 12729

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of Mangalore

No. in Reg. Book 30485 Survey held at Mangalore Date, First Survey Last Survey 6-4-1949

TONNAGE :- Built at Stockton By whom Craig, Taylor & Co. Ltd. When 1918

Owners British India Steam Navigation Co. Ltd. Managers

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

N.B.—All alterations in the existing records should be underlined.

st Report, No. 7740. Port Suez.

ical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete

amage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? if so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR

PRIMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faired or Repaired								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Planking of Decks	Celling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Stairways	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Stairways & Fastenings	Rudder	Scuppers	Boats
Side Plating	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
" in way of sidelights	Windlass	Hatches	Condition, how ascertained
Frames	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
Longitudinals	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
Transverses	Have Watertight Doors been examined and found efficient?	Treenails	Anchors, No. of
Stairways	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
Inner Bottom Plating	Air and Sounding Pipes	Transoms, Pointers & Crutches	" length mean diam.
Have the Tanks been examined internally?	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	(on board.)
Have the Tanks been tested?		" " at other places	Rule length size
		Stringers, Clamps & Shelves	Chain Locker
		Salting	Hawsers & Warps
		State if examined.	Standing and Running Rigging
			Sails

General Observations, Opinion as to Class, Recommendation, &c. :- State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
Printing Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

TUES. 24 MAY 1949 Surveyor to Lloyd's Register of Shipping. Character Assigned



W1030-0176