

S.S. "UALAN"

It is submitted that Messrs. Grey & Hunter might be informed that the reason this vessel had not the Figure I assigned was that the equipment was not equivalent to the Rule, the anchors and cables had not been examined and compared with the Certificates, and a 3rd bower anchor is required.

Futhermore, the tests of the anchors and cables which are on board the vessel have been carried out by the Germanischer Lloyd's, and the case would have to be considered by the Committee.

FRG 1.3.20.



© 2020

Lloyd's Register  
Foundation

W1031-0074