

F.E.

Received from Chief Ship Surveyor

Rpt.

No. 6709

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/92.*)

Depth "d"

Description

Proportions

Length
Depth

BRIDGE Deck Sheerstrake

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed * 100A1 (Steel) as recommended.

† 100 A-1 ('Stub')

1 In (ett)

NB = Cull DBa 117 u 824 f 152 9786 FPT 776 APT 1254
 FK. 6 BH. Cunn. Lloyd at 60. P36 B108 F36



© 2020

Lloyd's Register
Foundation

W1031-0354

~~Angle, Plate, Tee Bulb, or Channel)~~
~~Angles on upper edge~~