

V.

8 = DEC 1944

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "MIDO" REPORT Hpl. No. 18598

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

A notation of "Examined L.R. 5.43" has been assigned.

The notation of "Examined L.R. 8.44" has been withheld for machinery.


Permanent repairs are required to buckled stem and bulwark plating (s.s.f) indented bulwarks etc. (p & s) and to slightly buckled frames in holds (p & s) at the Owners' convenience.

The WEST HARTLEPOOL Surveyors report this vessel placed in dry dock, bottom coated and no damage found due to striking a submerged object. Minor repairs effected.

IT IS SUBMITTED the vessel is eligible to have her present records maintained, subject as above. Its have record of docking survey 11,44.

11,44, Hpl, subject.

30.11.44



© 2020

Lloyd's Register Foundation

W1035-0116