

V.

25 APR 1944

.....
d by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

EL'S NAME "MUDO" REPORT Abn. No. 21331

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This vessel has the notation "Examined L.R. 5.43" valid for 12 months.


A stream anchor requires to be placed on board at the first opportunity. Permanent repairs are required to buckled stem and bulwark plating (s.s.f), set in bulwarks etc. (p & s) and to slightly buckled frames in holds (p & s) at the Owners' convenience.

The ABERDEEN Surveyors report the vessel afloat and on account of damage the fore mast, rigging etc. renewed.


A stream anchor, as above, is now on board. (1)

IT IS SUBMITTED the vessel is eligible to have her present records maintained in the R.B.

As now, with above requirements, except (1).


21.4.44

Delete from S.R.L:-
Stream anchor.



© 2020

Lloyd's Register
Foundation

W1035-0126