

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

At S.S. Sagolana

Rpt.

Atl

No.

2627

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

82.84

Depth "d"

25.25

Framing: Table No.

Page 16

Description

Bull angle as

Longitudinal No.

35621

Proportions

Length

Depth

Approved 11.6

Shelter Deck Sheerstrake and strake below of approved thickness to give equivalent strength.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \pm 100A-1. (Steel) *Shelter deck* with freeboard," as recommended. The Summer freeboard of *4' 0"* from centre of disc to top of statutory deck line at *upper* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

\pm 100A-1. (Steel) *Shelter deck with freeboard*

1 Deck (Steel) & Shelter Deck (Steel)

WB. Bull 2B a 146 u 224 f 187 1350t DTA 36/368t API
FK. 73H. Cum. Lloyd's at 60.

P.T.O

W1054-0240

© 2021

Lloyd's Register
 Foundation