

by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

EL'S NAME Stl T.S. "N.T. NIELSEN - ALONSO" Rpt. OSL No. 4504

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02).

DAMAGE.

of Survey \_\_\_\_\_

Damage through Grounding Cause not stated (OSL 4408)

How repaired as follows:-

	Plates	Frames	R.Frames	Floors	Beams	Str.	Plates	Dk.	Plates
Renewed .....	1								
Removed and faired or repaired.....									
Faired or repaired in place.....	10								

Other items:-

Vessel placed on floating dock, bottom cleaned & coated  
No damage found through grounding.  
Minor repairs effected.

Some alterations have been effected in way of the upper deck railing in connection with the fitting of a Kirsner apparatus in accordance with approved plans.


is submitted the vessel is worthy to remain as classed with  
Record of Survey 3.35 as recommended.

100 A.I.

3.35 Sfg

ing whale oil etc etc  
for oil fuel etc

Delete from S.R.L. " vessel to be in dock



© 2020  
26 H. 35  
Lloyd's Register  
Foundation