

Custodian

flo 17720.


In view of the vessel being a Twin Screw Steamer  
it is submitted that the Surveyor be requested  
to state whether there are not six cylinders &  
six cranks instead of three as stated on  
his report.

Imd.

27. 2. 00

L.S.

27. 2. 00



2019

Lloyd's Register  
Foundation

W107-0201