

4 E

6 - NOV 1950

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "E LEMORE" REPORT Brs. No. 18003

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.*—Extract from Sub-Committee's Report, 24/5/92.)

Survey REPAIRS-TO-ENGINES-AND-BOILERS-DUE-TO DAMAGE THROUGH shortage of water.

A furnace, combustion chamber top and back plate of the boiler buckled.

The Surveyor reports the vessel is to be laid up pending Owners' decision regarding repairs and he recommends permanent repairs being carried out before vessel is placed back into service.

IT IS SUBMITTED action be deferred.



© 2020

Lloyd's Register Foundation

W1087-0229