

WRECK SECTION
7 JUN 1952
No. 54842
REPORT OF SURVEY FOR REPAIRS, &c.
5th June 1952
Port of CARDIFF
Survey held at CARDIFF
Date, First Survey June 3rd. Last Survey June 4th. 1952.
on the Wood, Iron or Steel Sc. "STEFANOS S".
No. of Visits 2

TONNAGE: - Built at Ayr By whom Ailsa S.B.Co.Ltd. When 1904 11.
ROSS 646 Owners P.Samonas. Owners' Address
NDER DK. 438 Managers -- Port belonging to Piraeus.
ET 256

veyed Afloat or in Dry Dock? Afloat Name of Dock East Dock. Destined Voyage
IDBorDBa feet; uE & B feet; f feet
l capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.
N.B.—All alterations in the existing records should be underlined.
st Report, No. 56942. Port Cpf.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)
CHARACTER: * for Special Survey. Date of last Survey and of Periodical Surveys.
100 A1 LMC.
1.50. M.S.11.45
ss.Bry.-8,47(Dr) B.S.12,49
O.G.2,50.
Laid up pending repairs - class suspended.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined -
Society's Freeboard (if assigned) as painted on Ship and now verified - ft. - ins.
Was a damage report made by anyone else? if so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR Interim Certificate - copy herewith.
ow done:-

Tanks and bilges sounded at 3 pm. of 3/6/52 and again at 12 noon of 4/6/52 and no variation found in soundings.

Hatches battened down under 2 tarpaulins and rudder lashed. fast.

Vessel is in my opinion in an efficient condition to be towed from Cardiff to Newport or other port in Bristol Channel to be broken up.

MARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ...								

ENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
ing of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
ngs	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
& Fastenings	Rudder	Scuppers	Boats
e Plating	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
" In way of sidelights	Windlass	Hatches	Condition, how ascertained
s	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
e Frames	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
udinals	Have Watertight Doors been examined and found efficient?	Treenails	Ancors, No. of
erses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
as	Air and Sounding Pipes	Transoms, Pointers & Crutches	" length mean diamr.
rs	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	(on board.)
Bottom Plating		" at other places	" Rule length size
ne Tanks been examined internally?		Stringers, Clamps & Shelves	Chain Locker
ne Tanks been tested?		Salting	Hawsers & Warps
		State if examined	Standing and Running Rigging
			Sails

General Observations, Opinion as to Class, Recommendation, &c.:
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."
This vessel is eligible in my opinion to remain as now classed viz, (laid up pending repairs - class suspended).

Int.Cert. 10 10
Fees applied for, 4 June 1952
Received by me, 4 June 1952
Second Surveyor's Fee (if any)
Committee's Minute
Character Assigned

TUES. 1 JUL 1952
Deferred - awaits further info
Lloyd's Register Foundation
W1092-0147