

Date of writing Report Oct. 18 1920 When handed in at Local Office 1-15 1920 Port of Milford Haven

Reg. Book. 61747 on the ~~Wood, Iron or~~ Steel Steam Hauler James C. Fell Master YEAR. 1918 MONTH. 12

UNDER DK. 250
116
Owners' Address ✓
(See also Appendix to Register Book).

WB=CellDBorDBa	✓	feet; U&B	feet; 1.	feet; 1.	feet; 1.	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
total capacity	✓	tons. FPT	tons. APT	tons; MT	feet	tons.

✓ Functions in the existing records should be underlined.

CHARACTER.	Feet	U&B	Machinery and Boiler
------------	------	-----	----------------------

Last Report, No. _____ *Port* _____ *attached*

cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the particulars should be clearly stated in the space provided on the back of the report, the particulars should be clearly stated in the space provided on the back of the report.

replacement of Anchors or Chains is required, the back of this form. State also the dates and initials of any letters respecting this case. painted on Ship and now verified {

In damage cases where the Surveyor has not made a special damage report he is required to state whether he entered his office and if so, whether they were declined? ☒ Was a damage report made by anyone else? If so, by whom? ☒

REPAIRS, OR EXAMINATION" AS PER ~~RULE, FOR~~ Admiralty request, Special survey No 3.

The vessel was examined in dock, at which time, the
stowage and bunkers being cleared and all ceiling lifted.

The deck, masts, rigging, hatches, ventilators, windlass, steering gear,

hand pumps and general equipment were examined.

It was not considered necessary to use the snail.
No side lights are fitted.

Repairs:- Shell and bulwarks faired as necessary.

Steelwork scraped and recoated.

SUMMARY OF DAMAGE REPAIRS	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items.
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Inner Bottom Plating	State if Tanks have been examined inside	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalt <small>(State which.)</small>	Rudder	Steering gear and its connections	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?
Decks	<i>good</i>												
Caulking of Decks	"												
Waterways	"												
Coamings	"												
Beams & Fastenings	"												
Outside Plating	"												
Caulking of ditto	"												
Rivets	"												
Breasthooks & Crutches	"												
Transoms	"												
Frames	"												
Reverse Frames	"												
Floors	"												
Keelsons	"												

Dblng. Plates under Sounding Pipes	Engine Room Skylights	Coal Bunkers, Open'gs, Lids, &c.	Scuppers	Cargo Hatchways	Hatches	Planking of Wood Vessels	Caulking ditto	Treenails ditto	Breasthooks & Stemson ditto	Transoms, Pointers, & Crutches ditto	Timbers of Frame at openings ditto	Ditto ditto at other places ditto	Stringers, Clamps & Shells ditto	Salting ditto
<i>good</i>	<i>good</i>	"	"	<i>none</i>	<i>good</i>									

Copper, or Y.M. of Wood Vessels	When put on, Month	Year
<i>(State if on Gold)</i>		
Boats		<i>go</i>
Masts, Yards, &c.		
Condition, how ascertained		<i>examined</i>
<i>(State if wedges removed)</i>		<i>no</i>
Sails		<i>good</i>
Equipment letter		
Anchors, No. of		<i>28. 1K.</i>
Cables <i>(State if now ranged)</i>		<i>Yes</i>
" length <i>105 1/2</i> size <i>1</i>		
" <i>(on board)</i>		
" Rule length <i>105</i> size <i>1</i>		
Hawser & Warps		<i>ly</i>
Standing & Running Rigging		

General Observations, Opinion as to Class, Recommendation, &c.—

State clearly whether any and if so, what alteration is suggested in the following: "to remain as classed and to have record of this survey, thus, for example:—.....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of *ss No. 1-15 and ptND15, &c.*"

The vessel is in good and efficient condition and eligible, in our opinion, to remain as classed with record of survey 10,20 and notation S.S. Milford Haven No 3 10,20.

Fees applied for. 2-11-2

Survey Fee (per Section 25)	£	1000	19	<i>Johnstone</i>
Special Damage or Repair Fee (if any)	£			
		Received by me		

Travelling Expenses (if chargeable) £ 19

Second Surveyor's Fee (if any) £

ERL NOV 19 1920

© 2021

Committee's Minute
Character Assigned

Spy Drunk
3.10.20

Longshore
