

Do. in peaks

6 2913 13 6 2913 13

Hold
Quarter 'tween Dks.

10x14 A2
10x163
AT HATCH ENDS

W1098-0099

2500, 12, 19.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "SENECA" Report Ch. No. 259

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24.5.02.)

Nature of Survey

When due

21 100 A.1. (steel)

1 Dk. (steel)

Cell DB 204' 515t. FPT 57t. APT 89t.

FK. 4BH. Jkt. cam. AYCP P27, B64', F26'

Date of Build 10, 20.

17/12/20

M AEB
1-12-20

The Surveyors should be requested to state whether the rivets in frames are spaced 7 diameters apart as required, also date of launch.



Lloyd's Register
Foundation

BEAMS, Second Deck, Single Angle, Bulb
Angle, Plate, Tee Bulb, or Channel

Deck. Material & thickness