

16 NOV 1925

Surveyors 16.11.25

Received from Chief Surveyors \_\_\_\_\_

NAME Aux. S.V. Cap WoodReport Cpu.No. 783For the **CHIEF SHIP SURVEYOR** and **CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 245/92.)

No. SB SURVEY PARTLY HELD.7.25

When proposed to be completed \_\_\_\_\_

Survey held, &amp;c., \_\_\_\_\_

To complete the donkey boiler survey due 7.25 & partly held in 8.25. The safety valves require to be adjusted. & the feed donkey tested under working conditions

The crank shaft of the port side oil engines requires to be renewed.

The Owner states that the vessel is proceeding to Copenhagen to be laid up & the above items will be dealt with before she proceeds to sea.

It is submitted action be deferred.

*HW*  
16/11/25  
*h*

© 2020

Lloyd's Register  
Foundation