

The most serious defect in this vessel appears to have been the entire omission of edge bolting throughout the ceiling which

Wood Motor Schooner "ELIZABETH RUTH".

It is submitted that action in this case be deferred for the present, pending the receipt of a further report after the vessel has been examined in dry dock as now recommended by the Surveyor.

Ct. 31. 5. 19.



© 2020

Lloyd's Register
Foundation

W1104-0281

LONDON.

SECRETARY TO THE
AMERICAN COMMITTEE.