

2 notation of 2 examined 8-40 valid for 6 months
has been assigned

Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

S NAME "PENNLAND" Rpt. Bel No. 12843

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The BELFAST Surveyors report this Dutch vessel, which was formerly classed with the Germanischer Lloyd, placed in dry dock and the bottom coated.

On account of damage through collision, shell plates N.9, O.8 and P.9 on starboard side found slightly indented and a port light broken. Temporary repairs effected.

The Surveyors recommend permanent repairs to Owners' convenience.

It is submitted the record 'Examined L.R. .40' be maintained in the Register Book, subject as recommended.

Insert in S.R.L

Surveyors' recommendation.

(Docking date 1.41) *[Signature]*



© 2020

Lloyd's Register
Foundation

W111-0088

[Signature]
20.1.41