

Do. of excess of Hatchways.
Do. above Crown of
Engine Room ..
Gross Tonnage

1521.06

Longitudinal Number

13998

Owners

Wm. Holt & Co. (L)

14.10

2m. 3.10.

1

Sent to Chief Surveyors 21/9/10

Received from Chief Surveyors

VESSEL'S NAME *Stl. S.S. "Thomas Holt"* Report *Grk.* No. *15870*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st Entry

When due

✱ 100A1 ('Stel') "Shelter deck with freeboard"
1 DR (stl) 8 web frames & Shelter deck (stl. Leaks) "Longitudinal framing"
WB = all DB a 67' vEBB 31' f115' 355t. APT. 31t.
FK. 5BH. Lem. Lloyds A.T.C.P.

M
R.A.
21/9/10
RETAIN

It is observed from the Report that the moulded breadth of the vessel is given as 31'-7 1/2" in place of 37'-9 1/2".

W1115-0141

Lloyd's Register
Foundation

Spacing
BEAMS, Third and Fourth Deck, Single Angle
Bulb Angle Plate Tee Bulb or Channel

Poop Deck Stringer Plate, breadth & thickness

Angle on ditto