



U.S. Pacific Iron (Co.)

over  
loaded to 50 lbs water pressure, new studs fitted. Inlet and exhaust valves renewed  
Rocker & cam shaft pedestals efficiently repaired and shaft tested. New packed  
regulating valve fitted.  
The whole unit satisfactorily tested upon completion of repairs under a  
load of 500 ampr.

Phunear

Damage due to broken bottom end  
Pelt. - also standard Aquamotive engine  
repaired.

In Mine aft starboard engine No. 120.  
No. 3 due to up. Broken. 6-12-12

It is concluded that the  
studs & bearings were engaged  
throughout but the damage  
is not confined to the  
new studs the part of  
stud which is  
fastened were  
broken or were  
cracked.

29/12/12



© 2019

Lloyd's Register  
Foundation