


S.S. "CHISWICK MANOR"

From the report received from the Cardiff Surveyors of their survey of damage repairs in January/February 1931, to which the Owners refer, it is observed that the vessel was examined in dry dock, the Nos.1 & 2 double bottom tanks were tested in way of the repairs and found satisfactory, and that the weather decks, hatchways, hatches, ventilators and equipment were generally examined and found or placed in order.

Should the Committee agree to the Owners' request regarding postponement of the Special Survey, it is submitted the Cardiff Surveyors might be asked to state if the parts enumerated above might be taken as part of the Special Survey No.3.

Attention is also called to the Owners' statement that while the vessel had been laid up, men have been employed in the upkeep of the hull and engines, and that the holds have been scaled and painted, and that at the present time the bunkers are being similarly treated.



23.6.32

© 2020

Lloyd's Register
Foundation

W121-0178