





The main boilers were examined internally and externally with their mountings, doors and fastenings and were found good except as below.

The following recommendations were made but have not been carried out.

Port boiler

The auxiliary feed valve chest to be removed.

The blow down valve chest to be removed.

The collision shock to be removed.

Steering engine

The piston rods to be skinned up and rebushed.