

Frame Amidships, Angle

Extends up to...

Margin Plate depth (excl. of flange) and thickness
Vertical Angle to Tank side

Chief Surveyors

Received from Chief Surveyors

SHIP NAME *Stl S. "SWAN"*

Report *Link*

No. *18704*


For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." -- Extract from Sub-Committee's Report, 24/5/92.)

Survey *1st Entry*

When due

✚ A. I. (Steel). "For River Towing Services in the Malay Peninsula"
1 D^k Leak
F.K, H.B.H, Cem, Lloyds A.C.P.



Frame and Reversed Frame joggled ?

Spacing