

Date 3rd. May, 1941.



No. of Items.....

SPECIFICATION of REPAIRS s.s. "BELGRAVIAN".

A.S. 187-5,000-5/40 (2000)-EW

DECK DEPARTMENT.

- Rudder stock packing to examine and renew if necessary.
- Rudder head chocks to be tightened.
- Dimmer Rheostat to fit to navigation lights.
- " " " " " shaded stern light.
- Signal yardarm to be raised 10 ft.
- Detachable length of voice pipe to fit between Conning Tower and E.R. speaking tube.
- Telescope & Binoculars to repair.
- Aximuth mirror to overhaul and adjust.
- Bridge clock to repair.
- Metal docking telegraph dial to fit.
- Wire reel brakes to repair.
- 2 threefold 10 ton blocks to be drilled and grooved for lubrication (Steering Gear). ~~xxxx~~
- Locks to overhaul and keys to supply in duplicate.
- Limbers in No.5 L.H. to renew and repair.
- Forepeak strum to clear.
- Rails to straighten where necessary.
- 8 Eyebolts to fit on boat deck.
- 1 Derrick tackle block to repair.
- 2 Cargo gyny's to repair.
- 2 double & 6 Single Guy blocks to repair.
- 1 Iron snatch block to repair.
- Vice to fit in Carpenters shop.
- Rounded Stem plate to be straightened.
- 1 Breast plate in way of same to straighten.
- Scuppers to clear in way of De-gaussing.
- Waterways to widen in way of lighter chocks.
- Bracket for Chem. Fire Exting. to fit in wheelhouse.
- Service pipe on After deck to repair.
- Ports in Crew's W.C. to make watertight and all ports in Crew's accom. to re-rubber and 2 port glasses to renew.



© 2021

Lloyd's Register  
Foundation

80 1334

W11254-0044 1/2





## SPECIFICATION of REPAIRS s.s. "BELGRAVIAN"

A.S. 187-5,000-5/40 (2880)-EW

DECK DEPARTMENT (CONTD).

30. Flush valves in Crew's W.C. to overhaul.
31. Battery box for W/T Emergency to be made watertight & portable rain shedder to fit.
32. Scupper hole to drill in Hospital bulkhead.
33. Gangway sides to repair or renew & 2 small eyebolts to fit at lower end.
34. 1 Accom. ladder stanchion to repair.
35. Outside tap to galley vase to repair.
36. Afterpeak sounding pipe to clear.
37. 1 Lifeboat hood to repair.
38. 1 Lifebuoy cleats abaft steering engine house to remove and refit on quarter rails.
39. Kite fitting on fore topmast to repair and stronger leading attachment to supply. (D.E.M.S.).
40. Several flags to repair.



© 2021

Lloyd's Register  
Foundation

W1120 0041 3/2