

Last Report, No. 10,451 Port 1 Nch

(Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

10041  
Examined 4.40 B.  
5.47 H.K. Leo  
Carrying petroleum TS  
in bulk. Fitter  
SC Feb No 3-6.35 F.P.

W1124-0166

n.11.38.

to Chief Surveyors

Received from Chief Surveyors

28 JUL 1911

SEL'S NAME

BRITISH CAPTAIN

Report

N.YK.

No. 41153

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

2<sup>ND</sup> No. 1 SURVEY PARTLY HELD.

due

6-39

When proposed to be completed

EXAMINED 5-41-12 MONTHS

on of Survey held, &c.. Examination of bottom, rudder, chain cables + chain locker. (11-39)

Bottom plating + riveting in all main cargo tanks (corrosion) to be again examined by 5-42 at latest.

was  
26.7.41

S.S. PART HELD

report for S.R.L

mined 5-41-12 months

end, as above.

(DOCKING DATE)  
5-41

S. N.Y.K.  
5/8/41

The Surveyors should be informed it is concluded the vessel is considered efficient for a period of 12 months but they should state if this is so and in all future similar cases the period of extension recommended should be inserted at the bottom of Report 8.

Floors	Have Watertight Doors been examined and found efficient?	Transoms, Pointers & Brutches	Chain Locker
Keelsons	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings	Hawsers & Warps
Stringers	Air and Sounding Pipes	" " at other places	Standing and Running R
Inner Bottom Plating		Stringers, Clamps & Shelves	
the Tanks been examined internally?		Salt	

Lloyd's Register  
Foundation