

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 22.1.43 When handed in at Local Office 22.1.43 Port of Bombay

No. in Survey held at Bombay
Reg. Book. on the Wood, Iron & SteelDate First Survey 18.12.42 Last Survey 20.12.1942
(No. of Visits 2)TONNAGE - Built at Glasgow By whom Harland & Wolff Ltd.GROSS 8466 Owners British Tanker Co. Ltd. Owners' Address
UNDER D.K. 7454 Managers Port belonging to London

NET 4913

YEAR, When 1939

MONTH, May

Surveyed Afloat or in Dry Dock? DD. Name of Dock Hughes Drydock Destined VoyageCell/Bord/Ba feet; uE&B feet; f feet | feet tons |
tal capacity tons. F.P.T. tons; A.P.T. tons; M.T. feet tons |

Only alterations in the existing records of tanks should be inserted.

N.B. All alterations in the existing records should be underlined.

Particulars of Classification (which must be inserted
precisely as in Register Book & Supplements)

CHARACTER.
For Special Survey.
Date of last Survey and of
Periodical Surveys.

100 A1-1.42
Carrying petroleum in
bulk

Machinery and Boiler
Surveys
(Including date of N.B., if any).

LMC 1.89
TSCL 1.42

Society's Freeboard (if assigned) as
painted on Ship and now verified

ft. ins.

Was a damage report made by anyone else? if so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR

Condition and DamageNOW DONE: Vessel in drydock: the bottom and rudder cleaned, examined
and recautched. Decks, hatches, ventilators and coaming examinedS.H. list Indented sheerstrake plate no. 7 and plate below examined
and found efficient.Damage stated caused by collision with tug "St. Athan" whilst
the vessel was leaving the No. 7 B jetty at Aberdeen on 29/11/42.Found shell plate hole from aft in port, 2nd above sheerstrake port side,
indented. Recommended plate to be removed, fairied and refitted at owner's
convenience. Plate meanwhile efficient

MARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Fairied or Repaired								
Fairied or Repaired in place								

PRESENT CONDITION OF THE	Good	Bulkheads	Engine Room Skylights	Good	Copper, or Y.M. (State if on Felt.)
Decks	Good	-	-	-	When fitted, Month
Caulking of Decks	-	-	-	-	Year
Coatings	-	-	-	-	
Fastenings	-	Rudder	-	Good	
Inside Plating	<u>Efficient</u>	Steering gear and its connections	-	-	
" in way of sidelights	-	Windlass	-	-	
Frames	-	Have pumps been examined and found effi-	-	-	
Transverse Frames	-	cient?	-	-	
Longitudinal	-	Have Sluice Valves been examined and found effi-	-	-	
Transverses	-	cient?	-	-	
Doors	-	Have Watertight Doors been examined and found effi-	-	-	
Seals	-	cient?	-	-	
Trimmers	-	Have Ventilators and their Coamings been examined	-	-	
Inner Bottom Plating	-	and found efficient?	Yes	-	
Have the Tanks been examined internally	-	Air and Sounding Pipes	-	-	
Have the Tanks been tested	-	Doubling Plates under Sounding Pipes	-	-	
			Engine Room Skylights		
			Coal Bunkers, Openings, Covers, &c.	-	
			Oil Bunkers	-	
			Scuppers	Good	
			Cargo Hatchways	-	
			Hatches	-	
			Planking	-	
			Caulking	-	
			Treenails	-	
			Breasthooks & Stemson	-	
			Transoms, Pointers & Crutches	-	
			Timbers of Frame at openings	-	
			" at other places	-	
			Stringers, Clamps & Shelves	-	
			Salting	-	
			(State if examined.)	-	

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

This vessel is eligible, in my opinion, to remain as classed with fresh record of survey 12.42. Subject to indenture sheerstrake plate no. 7 (55) and plate below being dealt with, and to 2nd from shell plate in port share side, 2nd above sheer, being fairied at owner's convenience

Survey Fee (per Section 29) £ 105/-

Fees applied for,

22.1.1943

Special Damage or Repair Fee (if any) £ 75/-

Received by me,

Travelling Expenses (if chargeable) £ 10/-

19.

Second Surveyor's Fee (if any) £ 48/-

Committee's Minute

TUES. 4 MAY 1943

Character Assigned

S12.42 Can put in bulk

John Rundle
Surveyor to Lloyd's Register of Shipping.

© 2021

Lloyd's Register
Foundation