

1

fees. paid.

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Twin Sc. "CLAN BUCHANAN" Report Grk. No. 20514

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First Entry.

When due _____

100A1 "With Freeboard ✓

2Dks. and Shelter dk. ✓


Cell.DB 393' 1266t, MT 39' 1360t, FPT 68t, APT 126t.

FK, Duct keel forward of Machinery Space, 7BH(Coll.BH to Shelter
Dk., 6BH to 2nd Dk.) pt.cem., Lloyd's A & CP. ✓

P 31', B 102', F 69'.

O.L.487.6'. ✓

This is generally a sister ship to the "CLAN CUMMING"



Lloyd's Register
Foundation

W1125-0069