

1m, 12, 41.

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME CLIFTON HALL

REPORT

LIV.

No. 117386

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE

When due

Subject to indented stem contour plate being dealt with and repairs being effected to fire damage to tween deck plating, shell plating, beams + frames adjoining Steward's Store (P.5) at the first convenient opportunity.

(H. W.)

was
11-3-42



© 2020

Lloyd's Register
Foundation

W1126-0121

Stringers.....

Have Ventilators and their Coamings been examined

Timbers of Frame at openings.....

at other places

Rule length

Chain Locker