

If the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material? **Yes**

If two liners are fitted, is the shaft lapped or protected between the liners **Yes**

If without liners, is the shaft arranged to run in

Is a gland - bearing length of stern bush **924 %**

Diameter of propeller **2**

W1127-0061

Total surf

Yes Thicker

pipes and siler

being syphon

with an effici

St

How d

os: - In engi

Sizes

Is a separate

Engine Room

the skin of th

the floor plate

sible on the p

ocks and val

✓

from saturat

25

80

✓

✓

so as to b

Cubic capac

of tensile str

✓

itudinal join

Is e

What me

P. S. Motor Vessel. "Primula"

The Genoa Surveyors report that the groove actuating cam roller N^o 2 on the port engine sustained damage during the trial trip & it has been arranged to fit a new shaft at the earliest opportunity.

It is submitted that


this vessel is eligible for

THE RECORD. + L MC. 6.21. Subject to the after length of counter shaft of the cam shaft of the port engine being renewed before the end of December 1921.

6 Oil Engines A.S.C. SA (Annual Survey)
12 cy 16 ¹⁵/₁₆" - 26 ³/₈" 221 NHP.

14 2 DB. (Doukey boilers) 100 lb.

Franco Tosi. Legnano.



Range of tensile strength 150

fitted with a safety valve as per Rule **Yes**

Can the internal surfaces of the receivers be examined **Yes**

inner surfaces **Loose flanges on bolts**

Is there a drain arrangement fitted at the lowest part of each